


Service Parts Model Nos. K-6952-F Alterna, K-7436-FL-F Flair, K-7436-DB-F Flair II, K-7436-T-F Triton II



A	05012	Countersunk Screw (CP)
B	29607	Hot Handle
	29608	Cold Handle
C	99100371	Escutcheon (CP)
D	99100372	Washer
E	99100373	Attachment Assembly (RP) (Includes E and K)
F	24972	Bonnet (CP)
G	33467	Hot Stem Unit (Plastic Plunger)
	334670	Cold Stem Unit (Plastic Plunger)
	37258	Hot Stem Unit w/ Brass Plunger
	372580	Cold Stem Unit w/ Brass Plunger
I	99100374	Valve Body
J	24442	Flexible Hoses (2)
K	99100373	Attachment Assembly (RP)
L	14602	2.2 GPM Small Slotted Male Aerator
M	NLA	Spout Assembly (CP)
N	99100359	Lift Rod (CP)
	NLA	Lift Rod w/ Square Top (CP)
O	99100370	8-32 x .562 Screw
	99161816	Lg Flair II Handle, Pair (CP)
	NLA	Flair II Handle

Schematic Reference Code KOH_THS_K69