


Component Parts

1/2" Check Stem and 1/2" Faucet Stems



A	99061024	Red Button
	99061025	Blue Button
B	99061023	10-24 X 1/2" Screw
C	NLA	Lever Handle (99101543 suggested replacement)
D	99061027	Bibb Cap
G	99060545	Washer
I	99101542	Spring
J	99061028	Seat Washer
K	99101568	Slot Round HD Screw
L	99101543	Lever Handle Repair Kit
M	99101544	RH 1/2 Check Stem Repair Kit
N	99101545	LH 1/2 Check Stem Repair Kit
O	99101546	Retainer Assembly
P	99101547	RH 1/2 Swivel Stem Repair
Q	99101548	LH 1/2 Swivel Stem Repair
R	99101542	Spring
S	99061024	Red Button
S	99061025	Blue Button
T	99061023	10-24 X 1/2" Screw
U	NLA	Lever Handle (99101543 suggested replacement)
V	99061027	Bibb Cap
Y	99060545	Washer
Z	37599	1/2 Swivel Stem Hot
	37598	1/2 Swivel Stem Cold
AA	99061028	Seat Washer
BB	99101568	Slot Round HD Screw